

Stewards Decisions - Teams  
2020 F4 United States and FR Americas Championships



Competitor	Car #	Class	Circuit	Session Date	Session	Article # / Offense:	Decision	Rep	Fine	Dec. #
Abel Motorsports	15	FR	Circuit of the Americas	24 October 2020	Qualifying	26.1/Technical Regulations 2.7.1/TAMFR-2020-027 - Non-compliant manner of assembly	Team reprimand	1	\$ -	604
Abel Motorsports	15	FR	Barber Motorsports Park	01 August 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	311
Abel Motorsports							Total Reprimands and Fines	2	\$ -	
Alliance Racing	28	F4	Circuit of the Americas	24 October 2020	Race 1	26.1 - Missing rear tow hook/15.5.1.j - Failure to follow instructions of officials	Team reprimand and fine	1	\$ 250	607
Alliance Racing	03	F4	Sebring International Raceway	27 September 2020	Race 2	26.9 - Video cards submitted late or without recorded video, or not submitted	Team fine	-	\$ 100	421
Alliance Racing	28	F4	Sebring International Raceway	26 September 2020	Qualifying	24.3 - Non-compliant qualifying or race tires	Team reprimand	1	\$ -	408
Alliance Racing	28	F4	Sebring International Raceway	25 September 2020	Practice 1	23.6 - Failed to complete pre-event scrutineering	Team fine	-	\$ 250	405
Alliance Racing	43	F4	Sebring International Raceway	25 September 2020	Pre-Event Tech	28.2 - Change of engine for any reason	Five grid places and team fine	-	\$ 2,500	402
Alliance Racing	28	F4	Sebring International Raceway	25 September 2020	Pre-Event Tech	28.2 - Change of engine for any reason	Five grid places and team fine	-	\$ 2,500	401
Alliance Racing	33	F4	Barber Motorsports Park	31 July 2020	Practice 1	24.5 - Non-compliant practice tires	Start at back of qualifying grid and three grid places at next race	-	\$ -	307
Alliance Racing	03	F4	Virginia International Raceway	17 July 2020	Practice 1	23.6 - Failed to complete pre-event scrutineering	Team reprimand	1	\$ -	203
Alliance Racing							Total Reprimands and Fines	3	\$ 5,600	
Andretti Autosport	68	FR	Sebring International Raceway	26 September 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	416
Andretti Autosport	68	FR	Sebring International Raceway	27 September 2020	Qualifying	Technical Regulations 2.7.1 and TAMFR-2020-027 - Non-compliant manner of assembly	Ten grid places and team fine	-	\$ 500	415
Andretti Autosport							Total Reprimands and Fines	1	\$ 500	
Crosslink/Kiwi Motorsport	13	F4	Circuit of the Americas	23 October 2020	Practice 1	28.2 - Change of engine for any reason	Rescission of Decision 502	-	\$ (2,500)	602
Crosslink/Kiwi Motorsport	13	F4	Homestead-Miami Speedway	02 October 2020	Practice 1	28.2 - Change of engine for any reason	5 grid places + team fine (penalties suspended pend further analysis)	-	\$ 2,500	502
Crosslink/Kiwi Motorsport	19	F4	Sebring International Raceway	27 September 2020	Race 3	26.9 - Video cards submitted late or without recorded video, or not submitted	Team reprimand and fine	1	\$ 250	428
Crosslink/Kiwi Motorsport	19	F4	Sebring International Raceway	27 September 2020	Race 2	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	422
Crosslink/Kiwi Motorsport	32	F4	Barber Motorsports Park	01 August 2020	Race 2	26.1/Technical Regulations 2.7.1 - Floor obtained from a source other than manufacturer	Start race from pit lane and team fine	-	\$ 1,500	313
Crosslink/Kiwi Motorsport	14	F4	Virginia International Raceway	18 July 2020	Qualifying	26.1/Technical Regulations 2.7.1 - Front brake rotor not as delivered/Type 1 part replaced from source other than manufacturer	Team reprimand and fine	1	\$ 250	207
Crosslink/Kiwi Motorsport	14	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	Protest - 26.1 - Alleged non-compliant flywheel	Protest disallowed	-	\$ -	127
Crosslink/Kiwi Motorsport	14	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	Protest - 26.1 - Alleged non-compliant fuel cell	Protest disallowed	-	\$ -	126
Crosslink/Kiwi Motorsport	14	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	Protest - 26.1 - Alleged non-compliant gear box (not as supplied)	Protest disallowed	-	\$ -	125

Stewards Decisions - Teams  
2020 F4 United States and FR Americas Championships



Competitor	Car #	Class	Circuit	Session Date	Session	Article # / Offense:	Decision	Rep	Fine	Dec. #
Crosslink/Kiwi Motorsport	91	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.9 - Video cards submitted late or without recorded video, or not submitted	Team fine	-	\$ 100	121
Crosslink/Kiwi Motorsport							Total Reprimands and Fines	3	\$ 2,100	
DC Autosport	51	F4	Virginia International Raceway	18 July 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	213
DC Autosport							Total Reprimands and Fines	1	\$ -	
DEForce Racing	22	F4	Virginia International Raceway	17 July 2020	Practice 2	26.9 - Video cards submitted late or without recorded video, or not submitted	Team reprimand	1	\$ -	205
DEForce Racing							Total Reprimands and Fines	1	\$ -	
Group-A Racing	62	F4	Sebring International Raceway	26 September 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	414
Group-A Racing							Total Reprimands and Fines	1	\$ -	
HMD Motorsports	99	FR	Sebring International Raceway	26 September 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	417
HMD Motorsports	55	FR	Mid-Ohio Sports Car Course	26 June 2020	Qualifying	26.9 - Video cards submitted late or without recorded video, or not submitted	Team fine	-	\$ 100	107
HMD Motorsports							Total Reprimands and Fines	1	\$ 100	
Iron Rock Motorsports	26	F4	Sebring International Raceway	27 September 2020	Race 3	26.1/Technical Regulations 2.7.1 - Non-compliant part	Team reprimand and fine	1	\$ 250	424
Iron Rock Motorsports	26	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	39.5(b) - Car worked on during a race suspension	Team reprimand	1	\$ -	116
Iron Rock Motorsports							Total Reprimands and Fines	2	\$ 250	
Jay Howard Driver Development	4	F4	Barber Motorsports Park	01 August 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified floor	Disqualification and team fine	-	\$ 3,000	312
Jay Howard Driver Development	6	F4	Barber Motorsports Park	01 August 2020	Race 1	26.1/Technical Regulations 2.7.1 - Oil pickup tube installed reversed	Five grid places and team fine	-	\$ 750	310
Jay Howard Driver Development	5	F4	Barber Motorsports Park	01 August 2020	Race 1	26.1/Technical Regulations 2.7.1 - Oil pickup tube installed reversed	Five grid places and team fine	-	\$ 750	309
Jay Howard Driver Development	3	F4	Virginia International Raceway	19 July 2020	Race 3	26.9 - Video cards submitted late or without recorded video, or not submitted	Team fine	-	\$ 100	229
Jay Howard Driver Development	3,4,5,6,8	F4	Virginia International Raceway	19 July 2020	Race 2	24.3 - Non-compliant qualifying or race tires	Team reprimand	1	\$ -	222
Jay Howard Driver Development	5	F4	Virginia International Raceway	19 July 2020	Race 2	28.2 - Change of engine for any reason	Five grid places and team fine	-	\$ 2,500	218
Jay Howard Driver Development	8	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	133
Jay Howard Driver Development	7	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	132
Jay Howard Driver Development	6	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	131
Jay Howard Driver Development	5	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	130
Jay Howard Driver Development	4	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	129
Jay Howard Driver Development	3	F4	Mid-Ohio Sports Car Course	28 June 2020	Race 2	26.1/Technical Regulations 2.7.1 - Modified engine oil pressure sensor	Disqualification and team fine	-	\$ 3,000	128

Stewards Decisions - Teams  
2020 F4 United States and FR Americas Championships



Competitor	Car #	Class	Circuit	Session Date	Session	Article # / Offense:	Decision	Rep	Fine	Dec. #
Jay Howard Driver Development	7	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	26.1/Technical Regulations 2.7.1 - Restricted or undersized engine oil suction screen assembly	Disqualification, team fine and start from pit lane at next 3 races	-	\$ 3,000	115 (a)
Jay Howard Driver Development	6	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	26.1/Technical Regulations 2.7.1 - Restricted or undersized engine oil suction screen assembly	Disqualification, team fine and start from pit lane at next 3 races	-	\$ 3,000	114 (a)
Jay Howard Driver Development	7	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	Technical Regulations 2.7.1 - Shock cover fasteners added	Team reprimand	1	\$ -	113
Jay Howard Driver Development	4	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	Technical Regulations 2.7.1 - Shock cover fasteners added	Team reprimand	1	\$ -	112
Jay Howard Driver Development	8	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	39.5(b) - Car worked on during a race suspension	Team reprimand	1	\$ -	109
Jay Howard Driver Development	7	F4	Mid-Ohio Sports Car Course	27 June 2020	Race 1	39.5(b) - Car worked on during a race suspension	Team reprimand	1	\$ -	108
Jay Howard Driver Development	11	FR	Mid-Ohio Sports Car Course	25 June 2020	Pre-Event Tech	26.1/Tech Regs 15.2.5/Ligier JS F3 Tech Memo #1 - Halo FIA label and hologram	Team reprimand and sealing and confiscation of component	1	\$ -	101
Jay Howard Driver Development							Total Reprimands and Fines	6	\$ 31,100	
(a) The Competitor lodged Appeals against decisions 114 and 115. On 17 July 2020, SCCA's National Court of Appeal rejected each Appeal and confirmed the decisions of the Stewards.										
New Gen Racing	87	F4	Sebring International Raceway	27 September 2020	Race 3	26.3(k) - Engine oil below minimum level	Five grid places and loss of points from the race	-	\$ -	425
New Gen Racing							Total Reprimands and Fines	-	\$ -	
Velocity Racing Development	29	F4	Sebring International Raceway	26 September 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	413
Velocity Racing Development	11	F4	Barber Motorsports Park	01 August 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	308
Velocity Racing Development	11	F4	Virginia International Raceway	18 July 2020	Race 1	26.3(b) - Fire extinguisher not in armed position for on track session	Team reprimand	1	\$ -	212
Velocity Racing Development							Total Reprimands and Fines	3	\$ -	