



## Formula Regional Americas Championship

### Road America

13 – 17 May 2021

<b>From</b>	The Stewards	<b>Document</b>	228
<b>To</b>	The Team Manager	<b>Date</b>	3 June 2021
	Crosslink Competition	<b>Time</b>	15:50

The Stewards, having received a report from the Technical Delegate (Document No FR-2021-02-01), have considered the following matter and determine the following:

<b>No/Driver</b>	9 – Joshua Car
<b>Competitor</b>	Crosslink Competition
<b>Time</b>	10:00 on 17 May 2021
<b>Session</b>	FR Round 5
<b>Facts</b>	During an inspection of the car's diffuser, the Series technical staff observed that the bolt securing the right hand diffuser tunnel to the gearbox attachment bracket was missing.
<b>Offence</b>	Breach of Article 26.1 of the Sporting Regulations read with Article 2.7.1 of the Technical Regulations.
<b>Decision</b>	Team fine of \$500 U.S. The Competitor is directed to assemble the car's diffuser in the proper manner prior to pre-event technical inspection for the next event.
<b>Reason</b>	Based on the Technical Delegate's rule violation report, the Stewards determined that the diffuser was assembled in an improper manner per Article 26.1 of the Sporting Regulations and Article 2.7.1 of the Technical Regulations.

The Competitor is reminded of his right to appeal in accordance with Article 16.2 of the Sporting Regulations except where the penalties are not susceptible to appeal (Articles 16.2.5 and 16.1.4.d of the Sporting Regulations).

Pat di Natale

**Steward (Chairman)**

Wesley Cunningham

**Steward**

John Walsh

**Steward**

#### Received by the Competitor:

Signature: \_\_\_\_\_ Printed name: \_\_\_\_\_  
Date: \_\_\_\_\_ Title: \_\_\_\_\_