

FR Technical Advisory Memo

Nº: TAMFR-2020-010

Date: March 9, 2020

Subject: Ligier Bulletin # 5 LH Radiator Outlet Bleed Kit

The attached bulletin describes parts required to add a bleed to the left side radiator. This update must be added to pass annual tech before competing in 2020 series events and remain in place for all subsequent events.

This kit is composed of Type 1 parts and must be installed as illustrated in the bulletin.

This is a mandatory upgrade.



RED LINI







